Approved For Release 2003/12/23: CIA-RDP33-02415A000300150056-0

25X1A 25X1A 25X1A

25X1 25X1A 25X1A 25X1A

25X1A

25X1A


25X1A

25X1A

25X1A

25X1A 25X1A

SECRET



1 December 1961

SUBJECT: Monthly Commander's Report
TO: Chief, DPD
A. General
1. The highlight of this months activity was the inspection visit paid to this unit by the on 9 November. While on the station he observed a perfectly executed takeoff and landing performed by in the buring this inspection tour also personally greated the local staff and spent approximately thirty minutes touring the various shops within our installation. Needless to say everything was in inspection shape and I believe that his visit provided a good boost morale wise for the The were especially pleased at the opportunity to demonstrate the performance of the by their crewmember.
2. The key social event of the month was the joint banquet held on 14 November. This banquet which was held at our hostel area was promoted by and as a result, several of their key people attended. A listing of the personnel in attendance other than our detachment types follows:
Guest List
3. I assumed command of this detachment on 15 November after a very comprehensive briefing and local orientation provided by The unit has been flying steadily during the month and I believe that the proficiency has reached its highest peak to date. I have been very favorably impressed by the proficiency displayed by the and the organization of the training program in general. The training program appears to be very solid even to the extent of a fine physical fitness program. I am convinced that the are operationally ready and capable of performing any assigned mission.

SECRET

Approved For Release 2003/12/23 : CIA-RDP33-02415A000300150056-0_DFA-0599

2

25X1A

25X1A

25X1A

25X1A

25X1A

rt sortie or to the	eir morale appear to the standdown po	ne P.	For the mo	nth of Bec r to gain :	ember we pl maximum pro	an numerou ficiency	18
Adminiet	tration						\neg

SECRET

3

C. Operations

25X1A

25X1A 25X1A

25X1A 25X1A

25X1A

l. During the month, eighteen training sorties were scheduled, of which fifteen were successfully completed. Two were cancelled due to weather and one was cancelled due to a tour of the installation by on 9 November. One early return occurred as a result of sump overflow light on and visual sighting of fuel venting. One late take off occurred due to detection of oxygen leak in exhalation valve after pilot was strapped in the cockpit. Leak was not detected on console check.
2. A total of 57:50 hours were flown in the, and 60:35 hours in the T-33. One demonstration flight of 15 minutes duration was flown accomplished during the period is portrayed by the attached chart. (See Attachment 2)
3. Two new training missions were developed and added to the library making a total of 32 training missions on file. Two periods of Flying Safety and Ground Training were conducted including a general briefing on survival and demonstration of equipment.
4. The was flown 5 times and twice. Two long range missions were scheduled, one of which was successfully completed — the other was an early return. CPX's were conducted on both missions for Flight Planners and the Photo Interpreter.
5. The are considered both proficient and combat ready for assigned missions, with the exception that the lack of large land areas in our training area results in limited Flight Line and Driftsight practice. The altitude restriction of 40,000 feet over the due to Chicom radar cover, winds in excess of 100 knots at 40,000 feet, and the persistent cloud cover over most of the Island preclude frequent use of the Island.
6. The one deficiency which I am concerned with was their reluctance to accept or attempt inflight feeding procedures. This problem is mainly psychological due to the lack of confidence in the

action to correct this and establish their confidence in the procedure. D. Materiel

All Materiel problems encountered during this period were within local capability to resolve. Conversion to new FAK listings and cards

psychological due to the lack of confidence in the capability of the equipment to function properly. Also their determination to pay strict attention to their work has a bearing on the problem. This meant that on certain longer flights they would be without water or food for periods up to twelve hours which brought about a weakened condition. I have taken

Approved For Release 2003/12/23 : CIA-RDP33-02415A000300150056-0 DFA-0594

4

was completed this month without affecting support capability. Need continues to exist for an additional air conditioner in the Flight Plans Office. A previous request to Headquarters for an additional air conditioner was denied. The number of personnel and the frequency of briefings, meetings and conferences held in that office justifies this unit.

:	E. Maintenance
25X1A	1. The following discrepancies occurred during the month:
	a. The sump tank overflow light came on during two flights. As a corrective action the tanks were flushed again.
	b. The flap light indicator for Gust malfunction came on during two flights. A new switch was installed eliminating this problem.
	c. Elevator trim tab run-away due to burnt out resistor in trim box.
	d. Fuel pressure fluctuation from 14 to 25 pounds. The flow regulator was replaced.
	e. Flap operation malfunction prior to landing. The hydraulic system was low on oil due to a split hose line to the speed brakes.
	f. The trim tab follow up unit failed in flight and was replaced.
25X1A	2. On 14 December will be due for PE Inspection with an ETIC of 28 December. During this period the following S/B's will be accomplished; 531, 536, 557, 584 and 586.
į	F. Security
25X1A 25X1	1. On 5 November the Director of Security was in the area and held a conference with the Security Staff. This meeting was held in
25X1A 25X1A 25X1A 25X1A	2. On 9 November visited the hangar area. He was accompanied by his staff and personal bodyguards. Pictures were taken of inside the hangar area. The pictures were taken by and the negatives turned over to Security. Photographers who accompanied were not permitted inside the hangar. The names of the individuals who entered the hangar were supplied to Headquarters via

SECRET

25X1A

Approved For Release 2003/12/23 : CIA-RDP33-02415A000300150056-0DEA 0599

SECHET

5

25X1	1Δ	
25X 25X	3. On II November the presented with a A commendation and a set of wings. A select group of project cleared individuals attended this presentation which was held in a conference	25X1A
	4. Pictures were taken during the anniversary banquet mentioned in my opening paragraph. Distribution of these photographs is controlled and no compromising prints of this affair will be distributed.	
	G. Personal Equipment	
	Inflight feeding familiarization training became effective 29 November. The were instructed in inflight feeding procedures, a demonstration was given and safety hazards and precautions thoroughly discussed. Each sampled the various foods in an effort to determine their preferences for re-order purposes.	25X1A 25X1A
	H. Installations	-
	The following Station improvements and routine preventative maintenance was accomplished during the month:	
	a. Hostel area improvements mainly consisted of the construc- tion of a very fine fireplace in the mess-bar area. The cost of \$350 was provided for by profits from the local bar fund. This will help improve the atmosphere during the approaching cold weather period. Also in the living area we initiated a preventative main- tenance program on the 26 window type air conditioning units. Labor is being provided by an outside contractor at a cost of \$5 per unit. This program will be completed in December.	
25X 1	b. Hangar area improvements consisted of a wind velocity and direction indicating unit installed in the office for use of the Heather Officer. This indicator is a remote unit operating off of the existing installation in our Operations Office. The installation of a 50' telephone pole and two 225' long wire antennas to the hangar has been completed. This installation is for emergency back up communications.	25X1A
		25X1A
05)/	5 Inclosures 1. Breakdown of November expenses, 1 copy, h/w	
25X ²	3. 9 November photo of visit, 1 copy, u/s/c 4. 14 November photo of anniversary banquet, 1 copy, u/s/c	
	5. Identities, in trip, u/s/c	
	Approved For Release 2008/12/23: PIA-RDP33-02415A000300150056-0	Ì